

TEM Work on Unit 1

OFA

- Whelbox plates, turning vanes
- SA turning vanes
- Camera Ports
- ~~- Stabilizer & burner work~~
- Remove steam cool spacer brackets.
(Stamps)
- Blue Paint around soot blower.
- Extra work to install test ports (Ken)
 - Alignment bars and shields (Stamps)
- ~~- hatches~~